

## United States Department of the Interior

BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT Gulf of Mexico OCS Region 1201 Elmwood Park Boulevard New Orleans, LA 70123-2394

March 3, 2021

Mr. David A. Carmony EnVen Energy Ventures, LLC 609 Main Street, 3100 Houston, Texas 77002

Dear Mr. Carmony:

Reference is made to EnVen Energy Ventures, LLC's (EnVen) Right-of-way (ROW) modification application (TIMSWEB submittal ID: 195078874) received by the Bureau of Safety and Environmental Enforcement (BSEE) Pipeline Section on January 20, 2021, for Pipeline Segment Number (PSN) 19876, associated with ROW No. OCS-G 29383.

Specifically, EnVen requests a temporary cessation of operations for PSN 19876 until April 1, 2021. PSN 19876 has been out-of-service since January 29, 2020. The temporary cessation of operations is being requested due to several unsuccessful attempts to dislodge a stuck pig in Walter's PSN 10595.

The table below describes the pipeline segment pertaining to the aforementioned application:

PSN	Size (NPS)	Length (feet)	Service	Origin	Termination
				Platform A	Platform A
19876	6	17,511	Bulk Oil	Ship Shoal Area	Ship Shoal Area
				Block 227	Block 243

Pursuant to 30 CFR 250.1000(b), EnVen's application is hereby approved subject to the following conditions:

- 1. The annual rental required by 30 CFR 250.1012 shall continue to be due and payable in December of each calendar year.
- 2. If the associated pipeline has not been returned to service and is not being used for the purpose for which the pipeline ROW grant was made by April 1, 2021 the ROW grant shall be deemed expired in accordance with 30 CFR 250.1014. As a reminder per 30 CFR 250.1010(h) the ROW holder must remove all pipeline segments and accessories associated with ROW No. OCS-G 29383 within one year of the effective date of the relinquishment or forfeiture (i.e. expiration). Furthermore, a decommissioning application must be submitted to the BSEE Pipeline Section to decommission PSN 19876 within 30 days from the effective date of the relinquishment or forfeiture (i.e. expiration).

Mr. Carmony 2

3. If at any time prior to April 1, 2021 it is determined that the use of PSN 19876 is to be permanently discontinued, an application to decommission the pipeline and relinquish the pipeline ROW shall be submitted to the BSEE Pipeline Section.

EnVen is hereby reminded of the following regulations since PSN 19876 was not returned to service on or before January 29, 2021:

- 1. Pursuant to 30 CFR 250.1006(b)(2), the subject pipeline segment must be flushed and filled with inhibited seawater.
- 2. Pursuant to 30 CFR 250.1003(b)(1), the subject pipeline segment must be hydrostatically tested for at least eight (8) hours at a stabilized pressure of a minimum of 1.25 times the Maximum Allowable Operating Pressure (MAOP) prior to return to service.

Sincerely,

**BIMAL** SHRESTHA Date: 2021.03.03 16:28:37 -06'00'

Digitally signed by **BIMAL SHRESTHA** 

(for) Stephen P. Dessauer Regional Supervisor Regional Field Operations